

1-6-76

32	33	T245	RBW
<hr/>		4	T255

FD:

ONE ORIGINAL & TWO ~~RES~~ 1962
RESURVEY BEARING TREES AS FOLLOWS:

AN ORIGINAL 48" D. FIR, IN GOOD CONDITION,
BARK SCRIBING VISIBLE, BEARS
N 42° W 60⁺ FT.

AND RESURVEY TREES AS FOLLOWS:

A 24" HEMLOCK, ALIVE. WITH SCRIBING
VISIBLE ON UNHEALED BLAZE, BEARS
N 30° E 98[±] FT.

AND A 62" D. FIR, IN GOOD CONDITION, BARK
SCRIBING DESTROYED BY LOGGING OPERATIONS,
BEARS N 16¹/₂° W 87[±] FT. WE RESCRIBE
ON BARE WOOD "T245 RBW S32 CS BT"
ON A SINGLE BLAZE.

DIETZGEN NO. 3855-6

X ~~ATK~~
S. File No. 592-3

WE FIND THE BRASS CAP SET IN 1962
LYING ALONGSIDE A BEARING TREE.

WE RESET THE GOVERNMENT MONUMENT
IN IT'S PROPER POSITION WITH RESPECT
TO THE FOUND BEARING TREES. THIS
MONUMENT IS MARKED AS DESCRIBED IN
THE OFFICIAL RECORD; WE ADD THE
MARKINGS "CS 1976" TO THE BRASS
CAP.

THIS CORNER IS LOCATED ON THE EAST
BANK OF A SMALL STREAM ALONG AN
E-W CUTTING LINE AT THE NORTH EDGE
OF A CLEARCUT.

COMPASS DECLINATION SETTING: 20° EAST

1-6-76

Gary L. Langley

A. Vic CANGIE

JERRY JACKSON

DENNIS JOHNSTON

OK
JAL

59/2-3