

6-10-76

27 | 26
34 | 35

T225 R5W W.M.

(SEE REN. #45)

FD:

A 1" IRON PIPE PROTRUDING 1/4 INCHES OUT OF THE GROUND, WITH BRASS CAP ATTACHED, MARKED:

COUNTY SURVEYOR'S OFFICE

T225

327 | 326

334 | 335

R5W

1958

FROM WHICH:

A 36" INCENSE CEDAR IDENTIFIED IN 1958 AS AN ORIGINAL BEARING TREE (SEE REN. #45) BEARS N 30° W 19' FT., WITH SCRIBE MARKS VISIBLE IN UNHEALED RESCIBE BLAZE.

A 12" W FIR, NOW A 20" ROTTEN SNAG BEARS S 81° W 38' FT., WITH SCRIBING " T225 R5W 334 CS BT" VISIBLE ON AN UNHEALED DOUBLE BLAZE.

(SEE REN. #45)

DIETZEN NO. 385-6

SW 39³ @ 10° 392

SE ~~64~~ @

NEW SW BT

15" ALDER T22S R5W S34 CS BT

S45°W 10⁴ LVL

NEW NW BT

9 ~~10~~" YEW T22S R5W S27 CS BT

N64°W 29² LVL

AN 18" NOW 24" D. FIR, ALIVE AND WELL-HEALED
BEARS S 31° E 62⁹ FT. (SEE REN. #45)

A 4" YEW MARKED IN REN. #45 BEARING N 50° E
9⁸ FT. IS GONE.

WE FIND NO EVIDENCE OF THE ORIGINAL
MONUMENT OR ANY ADDITIONAL ORIGINAL
BEARING TREES.

WE MARK TWO NEW BEARING TREES AS FOLLOWS:

A 9" YEW BEARS N 64° W 29² FT.,
SCRIBED "TZZS RSW S 27 CS BT" IN A
DOUBLE BLAZE.

AND A 15" RED ALDER BEARS S 45° W 10⁴ FT.,
SCRIBED "TZZS RSW S 34 CS BT" ON A
DOUBLE BLAZE.

COMPASS DECLINATION SETTING: 20° EAST

6-10-76

Jay H. Langley

A. VIC CANBIE

C. S. File No. 59/15-16 JAMES H. COOK.

OK