

①

T30S R4W

6-10-76

S34 S35

(SEE CORNER RENEWAL # 144 A)

1/4

FOUND AT CORNER POINT:

A 1" X 30" I. PIPE. (RECORD CALLS FOR A 3/4" X 30" I. ROD.)

FROM WHICH:

A 12" NOW 16" FIR BEARS: S42°E 24.0 FT. TREE IS ALIVE WITH "35" VISIBLE IN PICHED OVER SCAR. (SEE REN# 144-A)

A 12" NOW 22" FIR BEARS: S74°W 21.0 FT. TREE IS ALIVE WITH WELL HEALED BLAZE. (SEE REN.# 144-A)

A 7" NOW 9" LAURAL BEARS: N43°W 13.6 FT. TREE IS A LIVE WITH "4S 34 BT" VISIBLE BARK SCRIBE.

SET AT TRUE CORNER POINT:

A 1" X 36" I. PIPE WITH BRASS CAP STAMPED:

"DOUGLAS CO. SURVEYOR
T30S R4W

S34 S35

1/4

1976

PLACED 1" I. PIPE ON NORTH SIDE OF CAP.

OETZGEN NO. 38856

266 ✓

U. S. File No. 59/15-16C

②


* NO NEW TREES.

COMPASS DEC 20° EAST

6-10-76

M. L. ENDRAD LADIG
PETER L. EARLE

* NOTE: TO REACH CORNER
APPROX 100 FT WEST OF RD
30-A-220 TO S. E. COR SEC. 34 THAN
NORTH 250 FT. TO 1/4 COR. WHICH
LIES IN NORTH-SOUTH CUTTING LINE.

OK


DIETZGEN NO. 385-6