

1-18-77

5 | 4
1/4

T215 R11W

(SEE REN. # 39)

FOUND:

A 1" IRON PIPE, FIRMLY SET ON A SE SLOPE,
EXTENDING 12" OUT OF THE GROUND, WITH
BRASS CAP ATTACHED;

MARKED:

COUNTY SURVEYORS OFFICE

T215

1/4 35 | 34

R11W

1967

AND THE REMAINS OF A 3/4" IRON PIPE, BADLY
RUSTED, FIRMLY SET AT THE BASE OF THE
BRASS CAP AS NOTED IN RENEWAL # 39.

WE FIND THE ROTTING REMAINS OF A ^{24"} CEDAR
STUMP S 88° E 9⁵ FT AS DESCRIBED IN

#88 ✓

NEW BT 24' D Fir S 30°E

" 1/4 S 4 CS BT "

23⁵ @ 33°

.8387

23.5

41 935

25161

16774

19709.45

23.5

41

19

RENEWAL #39, HOWEVER WE DO NOT IDENTIFY IT
AS AN ORIGINAL BT.

WE FIND NO EVIDENCE OF THE ORIGINAL NW
BEARING TREE.

BEARING TREES MARKED IN 1967 (REV. 39) WERE FOUND
AS FOLLOWS:

A 12" NOW 16" RED ALDER, ALIVE WITH SCRIBING "1/4 S"
VISIBLE ON PARTIALLY HEALED BLAZE BEARS
S 75° E 39¹/₂ FT.


AND A 19" NOW 22" RED ALDER, ALIVE WITH SCRIBING
"1/4" VISIBLE ON PARTIALLY HEALED BLAZE BEARS
S 18° W 50³/₄ FT.

WE MARK A NEW BT AS FOLLOWS: 119⁷/₈ FT.

A 24" D. FIR BEARS S 30° E ~~119~~ FT.,
SCRIBED "1/4 S4 CS BT" ON A DOUBLE BLAZE.

COMPASS DECLINATION SETTING: 20° EAST

1-18-77

Gary L. Langlet 
PETER L. EARLE

C. S. File No. 59/29-13

