

T 275 R 1W

DATE: 2-23-77

1/4 S 19

Condition Report On  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s RESURVEY 1902 & 1911 CS FILE 57/21

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) \_\_\_\_\_

1. A FIR (REC. 36) 34 INCH DIAMETER BEARS N 10° W 10  $\frac{1}{2}$  FEET.

BLAZE OPENED, OLD SCRIBING VISIBLE "1/4 S 24 BT"

2. A FIR 14 NOW 28 INCHES DIAMETER BEARS S 37° E 24  $\frac{1}{2}$

FEET (REC. S 40° E). NO SCRIBING FOUND, BLAZE IS CHOPPED

OUT.

#134 ✓

RENEWAL

Monument Set: (Procedure and Description) SET 1" x 3/4" IRON PIPE  
WITH BRASS CAP ATTACHED AT 1/4 CORNER AS DETERMINED  
IN FOUND OF THIS RENEWAL, BRASS CAP IS STAMPED  
" DOUGLAS COUNTY SURVEYOR "  
T 27 S R 1 W  
1/4 S 19  
1977

new Accessories: (Description)  
I REBLAZE OLD BEARING TREE (SEE FOUND #2)  
BEARING S 37° E 24± FEET. I SCRIBE "1/4 S 19 CS BT"  
ON SINGLE BLAZE.

Location and Comments: 20° E Compass Declination  
D.C.S.O. Agency  
CORNER LIES ON  
N-S CUTTING LINE. LARRY E. MONBEAN Party Chief  
TIMBER IS ON EAST. ~~James C. Mon~~ Notekeeper  
AS THE B.T. TO THE  
NORTHWEST IS THE KAREN CHENEY Witnesses  
ONLY EVIDENCE REMAINING

OF THE 1902/1911 SURVEYS I DO NOT REMOVE THE SCRIBING REFERING  
TO SECTION 24, ALTHOUGH THE 1911 NOTES INDICATE THAT THIS  
IS NOT A 1/4 CORNER FOR SECTION 24.

*OK*