

T 30 S R 6 W

DATE: 3-15-77

NW COR
DLC 45

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

SECTION 23

Previous Renewal #'s 30

Monument(s) Found: (Condition and Source) 3/4 INCH DIAMETER

IRON PIPE IN CUT BANK OF OLD NICKEL MINE ROAD
AT OR UNDER AN 8 NOW 16 INCH DIAMETER BLACK
OAK. TREE HAS OLD UNHEALED BLAZE.

Accessories Found: (Condition and Source) _____

1. A WHITE OAK 14 NOW ²¹ ~~24~~ INCH DIAMETER BEARS
S 86° E 26² FEET. TREE HAS WELL HEALED DOUBLE
BLAZE.

2. A BLACK OAK 14 NOW 24 INCHES DIAMETER BEARS
S 27 1/2° E 59⁶ FEET. TREE HAS FAINT BLAZE
VISIBLE.



RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments: 20° EAST _____ Compass Declination

DCSO _____ Agency

G. L. LANGLITZ _____ Party Chief

Larry / M... _____ Notekeeper

LARRY E. MONREAN _____ Witnesses

all