

DATE: 4-7-77

SURVEYORS
T305 R1W D1E1C
COUNTY
COR NO. 2 HES 195
1977

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

NONE - CORNER LOCATION FALLS
IN CENTER OF A SKID TRAIL.
ORIGINAL CORNER MONUMENT
DESTROYED.

Accessories Found: (Condition and Source) _____

A BROKEN & DECAYED 13" FIR STOB BEARS
S 10° 30' W, 58.08' SCRIBING VISIBLE "X2
HES 195 BT."

A 30" FIR STUMP BEARS S 35° W (RECORD
S 25° W) 64.02' OPEN & FIND SCRIBING
" 95 BT"

154 ✓

RENEWAL

Monument Set: (Procedure and Description) AT THE
INTERSECTION OF RECORD DISTANCES
FROM THE TWO ORIGINAL BEARING TREES,
SET A ^{2 1/2"} BRASS CAP FLUSH WITH THE
GROUND. PLACED A ^{2'x2'} MOUND OF STONE AROUND
THE DOWNHILL (SOUTH) SIDE OF THE PIPE.

New Accessories: (Description)
A 26" DOUGLAS FIR BEARS S 26° E, 22.2'
SCRIBED "X 2 HES 195 CS BT" ON A DOUBLE
BLAZE.

A 16" DOUGLAS FIR BEARS S 11° W, 20.9'
SCRIBED "X 2 HES 195 CS BT" ON A DOUBLE BLAZE
PLACED COUNTY B.T. TAGS ON BOTH.

Location and Comments:
CORNER LIES 75'
NORTH OF OLD
ROAD - USED FOR
FORMER LOGGING
ACCESS.

16° E (ROCK IN AREA) Compass Declination
U.S. F.S. Agency
DENNIS GAYLORD Party Chief
" " Notekeeper
WALT BARTON Witnesses

OK
[Signature]