

T 29 S R 8 W

DATE: 4-7-77

511	512
514	513

Condition Report Only
 Not Found
 X Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 123 & 1924 RESURVEY

Monument(s) Found: (Condition and Source) A U.S. GENERAL LAND
OFFICE BRASS CAP 4 INCHES ABOVE GROUND FIRMLY
IN PLACE AT THE SECTION CORNER, CAP IS STAMPED

T 29 S	R 8 W
511	512
514	513

1924

Accessories Found: (Condition and Source) ORIGINAL B.T.

1. A 36 INCH PINE NOW UPROOTED AND BADLY DECAYED
 BEARS N 54° W 20[±] FEET TO CENTER OF ROOT HOLE.

NO SCRIBING FOUND.

NO OTHER ORIGINAL B.T.s FOUND.
 (B.T.'s PER 1924 RESURVEY)

2. A FIR 12 NOW 15 INCH DIAMETER BEARS S 82° E 13[±] FEET.

TREE HAS WELL HEALED SINGLE GLAZE.

#169V

3. A FIR 10 NOW 20 INCHES DIAMETER BEARS S 66° W 4⁶ FEET. TREE HAS WELL HEALED BLAZE.

4. A 7 INCH FIR NOW A 10 INCH SNAG 10 FEET HIGH BEARS N 33° W (TO CENTER AT TOP OF BLAZE) 9² FEET

CENTER OF BASE OF ~~TREE~~ SNAG BEARS N 28 1/2° W. X SNAG HAS WELL HEALED BLAZE.
N.E. B.T. IS GONE.

RENEWAL

ACCESSORIES FOUND.

Monument Set: (~~Procedure and Description~~) TREES PER 1966 RENEWAL # 123

5. A 9 INCH D. FIR NOW A 15 INCH DIAMETER STUMP BEARS N 42 1/2° E 16⁵ FEET. BOTTOM OF BLAZE

REMAINING ON STUMP PARTIALLY HEALED SCRIBED "2 CS BT"

6. A 9 INCH DIAMETER FIR NOW UPROOTED BEARS N 72° W 15⁹ FEET. TREE BLAZED

FRAG. SOME SCRIBE MARKS VISIBLE, WE DO NOT OPEN BLAZE.

New Accessories: (Description)

1. A FIR 15 INCHES DIAMETER BEARS N 44° W 64⁹ FEET. TREE DOUBLE BLAZED

AND SCRIBED "T295 RB W 511 CS BT"

2. A MADRONE 40 INCHES DIAMETER BEARS N 25° E 48¹ FEET. TREE DOUBLE

BLAZED AND SCRIBED "T295 RB W 512 CS BT"

Location and Comments:

THIS CORNER LIES
AT THE CORNER OF
CLEAR CUTS TO THE
NORTHEAST AND
SOUTHWEST.

20° E
DCSD
LARRY E. MONREAN
Larry E. Monrean
ROD KIMBERLING.

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK [Signature]