

T 245 RIW

DATE: 5-4-77

$\frac{1}{4}$ $\frac{S30}{S31}$

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s ORIGINAL

Monument(s) Found: (Condition and Source) 2 INCH SQUARE WOOD
^{CORNER}
 POST AT $\frac{1}{4}$. POST NOT ORIGINAL MONUMENT.

Accessories Found: (Condition and Source) ~~ORIG~~ ORIGINAL B.T.S

1. A CEDAR 16 NOW 24 INCH DIAMETER BEARS N 22° E
 9³ FEET (REC N 27° E HITS EDGE OF TREE NEAR FACE).
 BLAZE PREVIOUSLY CHOPPED OUT, ROTTED. NO SCRIBING FOUND.

2. A HEMLOCK 8 NOW 12 INCH DIAMETER IS DEAD AND PARTIALLY
 UP ROOTED. TREE BEARS S 86 $\frac{1}{2}$ ° E 8⁶ FEET. BLAZE PREVIOUSLY
 PARTIALLY OPENED SCRIBED " $\frac{1}{4}$ ", WE OPEN MORE BLAZE AND

#123 ✓

c

FIND SCRIBED "S".

RENEWAL

Monument Set: (Procedure and Description) SET 1 INCH BY 30 INCH IRON
PIPE WITH BRASS CAP ATTACHED AT 1/4 CORNER, CAP STAMPED

" DOUGLAS COUNTY SURVEYOR "
T 24 S R 1 W
1/4 S 30
S 31
1977

New Accessories: (Description)

1. A HEMLOCK 7 INCH DIAMETER BEARS S 53° W 24° FEET. TREE
DOUBLE BLAZED AND SCRIBED " 1/4 S 31 CS BT "

2. A HEMLOCK 11 INCH DIAMETER BEARS N 25° W 30 1/2 FEET. TREE
DOUBLE
V BLAZED AND SCRIBED " 1/4 S 30 CS BT "

Location and Comments:

20° EAST
D C S O
LARRY E. MONREAN
Jerry E. Monrean
R. B. KIMBERLING
S. J. FLOUSE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]