

DATE: May 16 1977

T 29 S R 8 W

E 1/16 S12
 S13

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

1975

Previous Renewal #'s Dependent Resurvey, Shaner 1976

Monument(s) Found: (Condition and Source) (Ref. CS 58/82) A 2 1/2" Iron Pipe

protruding 7" above ground, with a BLM Brass Cap marked.

E 1/16 S12
 S13

1975

Accessories Found: (Condition and Source) A Douglas Fir

22" diameter, bears S 19° W, 143' distance, open single blaze marked E 1/16 S13 BT.

and a Douglas Fir 25" diameter, bears N 83° W, 94' distance (rec. 15 links), open single blaze marked E 1/16 S12 BT.



RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments: 20° E Compass Declination
DCSO Agency
Rod Kimberling Party Chief
Stephen John Flame Notekeeper
Karen Cheney Witnesses

OK
[Signature]