

DATE: 5-31-77

T305 R1E

N 1/4 56

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) A MOUND OF SEDIMENT-ARY STONE FOUR INS. HIGH, ONE FT. DIAM., WITH POSSIBLE TRACE "1" CHISELLED MARKING ON ONE STONE 5" x 3" x 2". FROM STONE MOUND BEARING TREE IS BEHIND HIGH STUMP 24 INS. DIAM. AND WAS PROBABLY DISTURBED BY LOGGING OPERATION - AN AGED PILE OF LOGS IS 20 FT SOUTHEAST

Accessories Found: (Condition and Source) FROM A POINT 2° FT S.E. OF STONE MOUND A 14 INS. DIAM. FIR STUMP AND LOG BEARS N 67° W 33° FT. FOUND SCRIBING, "3-" OTHER SCRIBING HAS BEEN AXED OUT AND TREE DIED WITHOUT ANY HEALING. A POSSIBLE STUMP HOLE BEARS S 73° W 17.2 FT (REG 18" DIAM FIR, S 57° E 33° FT., 18" DIAM. FIR S 73° W 17.2)

Page 1 of 1

C. S. File No. 59/34-26

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:

IF CORNER SET  
FROM S 1/4 SEC 31  
IT WOULD BE 05 FT  
NORTH OF MOUND  
OF STONE

20°E

DCSO

R. B. KIMBERLING

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK  
[Signature]