

T295 ~~R&W~~<sup>7</sup>  
S 17  
C → C  
E 1/6

DATE: 6-6-77

Condition Report On  
Not Found  
 Renewed  
Unrecorded  
Surveyed In  
Referenced Out

Previous Renewal #'s SEE M 28-69

Monument(s) Found: (Condition and Source) FROM M 28-69

FD:  $\frac{3}{8}$ " I ROD, FIRMLY SET, EXTENDING 4" ABOVE GROUND ON A  
STEEP AND BRUSHY NE SLOPE ABOVE OLALLA CREEK.

Accessories Found: (Condition and Source) FROM M 28-69

A 24" NOW 20" D. FIR, ALIVE WITH WELL-HEALED DOUBLE  
BLAZE BEARS S 23° E 46<sup>±</sup> FT

AND AN 18" NOW 17" G. FIR, ALIVE WITH WELL-HEALED DOUBLE  
BLAZE BEARS N 66° W 27<sup>±</sup> FT. (REC. N 64° W 27<sup>±</sup> FT.)

# 236 ✓

C. S. File No. 59/34 - 30 Page 1 of 1

C

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:

20° EAST  
DOUGLAS W. SUEVEROR  
GARY L. LANGLITZ  
Gary L. Langlitz  
PETER L. EARLE  
STEPHEN J. FRAUSE

Compass Declination  
Agency  
Party Chief  
Notekeeper  
Witnesses

OK  
