

T 295 R7W

C 1/4 + S 17

DATE: 6-14-77

Condition Report On  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) NONE

#242 ✓

Page 1 of 1

C. S. File No. 59/34-26

C

RENEWAL

Monument Set: (Procedure and Description) CORNER LOCATION DETERMINED  
BY INTERSECTION

OF LINES CONNECTING OPPOSITE  $\frac{1}{4}$  CORNERS OF SEC. 17, SET:

1" X 30" I PIPE, 26" IN THE GROUND ON STEEP AND BRUSHY NW SLOPE WITH

BRASS CAP ATTACHED, MARKED: DOUGLAS COUNTY SURVEYOR

T29S R7W

C  $\frac{1}{4}$  + S 17

1977

New Accessories: (Description)

A 15" D. FIR, SCRIBED "C  $\frac{1}{4}$  S 17 CS BT" ON A DOUBLE BLAZE,  
BEARS N 31° E 45<sup>8</sup> FT.

AND A 22" D. FIR, SCRIBED "C  $\frac{1}{4}$  S 17 CS BT" ON A SINGLE BLAZE,  
BEARS S 54° E 23<sup>8</sup> FT.

Location and Comments:

20° EAST

Compass Declination

DOUGLAS CO. SURVEYOR

Agency

GARY L. LANGLITZ

Party Chief

Gary L. Langlitz

Notekeeper

KAREN CHENEY

Witnesses

STEPHEN J. FLAUSE

OK 