

T215  
 $\frac{1}{4}$   $\frac{54}{59}$   
R11W

DATE: 6/15/77

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s #43, #80

Monument(s) Found: (Condition and Source) BRASS CAP MARKED

COUNTY SURVEYOR'S OFFICE  
T215

$\frac{1}{4}$   $\frac{54}{59}$   
R11W  
1967

SET 12 INS. ABOVE GROUND

Accessories Found: (Condition and Source) 9 INS. NOW 14 INS. D. FIR

BEARS N 56° W 11 $\frac{3}{4}$  FT WITH WELL HEALED DOUBLE BLAZE.

A 7 INS. DIAM. ALDER, DOWN AND ROTTING, APPROX. ORIG.

LOCATION S 45° W 23 $\frac{1}{2}$  FT, DOUBLE BLAZED AND SCRIBED

" $\frac{1}{4}$  59 CS BT." A 14 INS. NOW 15 INS. D. FIR BEARS

N 9 $\frac{3}{4}$ ° E 23 $\frac{3}{4}$  FT, SINGLE PARTIAL HEALED BLAZE AND

SCRIBED "T215 R11W S  $\frac{1}{4}$  54." A 14 INS. D. FIR BEARS

Page 1 of 1

C. S. E. No. 59/34-40

S 9 1/2° E 49<sup>?</sup> FT., SINGLE PARTIAL HEALED BLAZE AND  
SCRIBED "T215 -- W N 1/4 59"

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:

20° E

Compass Declination

DCSO

Agency

~~R. H. G. LANGLITZ~~

Party Chief

R. Kimberling

Notekeeper

P. EARLE

Witnesses

OK  
JH