

T 20 S

R

DATE: 8-2-77

S 33

E 1/16

—●—

"

S 4

W

T 21 S

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

(T21-11)

Previous Renewal #'s 56 (SET BY R.E. STUNTZNER)

Monument(s) Found: (Condition and Source) 1 INCH DIAMETER

IRON PIPE.

Accessories Found: (Condition and Source)

1. A HEMLOCK 30 NOW 31 INCH DIAMETER

BEARS N 16 1/2° E 30.3 FEET (RECORD N 15° 45' E).

TREE HAS PARTIALLY HEALED BLAZE WITH

SCRIBING VISIBLE "S 33 1/16".

2. A 24 INCH CEDAR NOW A STUMP BEARS

S 49° W 7.5 FEET. STUMP HAS BLAZE

Page 1 of 1

FD OK

U.S. FILE NO. 59/38-11

C

WITH SCRIBING VISIBLE " S 4 E 1/4 "

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:	<u>20° EAST</u>	Compass Declination
	<u>DCSO</u>	Agency
	<u>LARRY E. MONREAN</u>	Party Chief
	<u>Larry E. Monrean</u>	Notekeeper
	<u>MIKE CLINE</u>	Witnesses

OK *[Signature]*