



DATE: 9-6-77

- Condition Report On
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) _____

ORIGINAL 5" FIR BIT, IS DOWN. (THIS HAS BEEN DETERMINED TO BE THE SW BT FOR THE FACE IS LESS THAN 2" RADIUS FROM THE CENTER OF THE LOG.) STUMP BEARS S55°W, 7.26'. SCRIBING VISIBLE ON DOUBLE

#5 ✓

BLAZE " 1/4 S BT "

THE S.E. BEARING TREE IS GONE.

RENEWAL

Monument Set: (Procedure and Description) A 2 1/2" BRASS

CAP ON A 1" IRON PIPE STAMPED AS

SHOWN ON REVERSE. SET BY

REFERENCE TO STUMP ~~AT~~ LOCATION

OF REMAINING ORIGINAL B.T.

New Accessories: (Description) A 11" LODGEPOLE PINE

BEARS S 11° E, 36.6' SCRIBED " 1/4 S 33

CS BT " ON A DOUBLE BLAZE.

A 8" LODGEPOLE PINE BEARS S 37° W,

45.7' SCRIBED " 1/4 S 32 CS BT " ON A

DOUBLE BLAZE, PLACED COUNTY B.T.

SIGNS ON BOTH.

Location and Comments:

20° E

Compass Declination

U.S.F.S.

Agency

DENNIS GAYLORD

Party Chief

" "

Notekeeper

TRAVIS WORTHEN

Witnesses

OK
[Signature]