

T265 R3W

DATE: 9-28-77

S11 | S12

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s #36

Monument(s) Found: (Condition and Source) <sup>DIAM.</sup> A 1 1/2" ALUM. ALLOY PIPE  
 12" ABOVE GROUND

Accessories Found: (Condition and Source) A 36" NOW 26" DIAM. FIR  
~~SNAG~~ STUMP, BADLY ROTTED, BEARS S15°W 7<sup>6</sup> FT. (O.B.T REC.  
 S10°W 6<sup>6</sup> FT.), A 15" NOW 20" DIAM. CEDAR BEARS S59°W  
 (REG (REN. #36 S44°W TO A 15" FIR) 56<sup>1</sup> FT., FOUND PARTLY  
 HEALED BLAZE AND SCRIBING "S11CS". A 12" NOW 30" DIA.  
 S. PINE BEARS N59°W 53<sup>5</sup> FT. WITH A WELL HEALED BLAZE  
<sup>5" NOW</sup>  
 A 18" DIAM. YEW BEARS S16°E 29<sup>7</sup> FT. WITH A WELL

#212 ✓

HEALED BLAZE. (PINE AND YEW MARKED BY HALE  
1946)

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:

20°E  
DC 50  
R. B. KIMBERLING  
R. B. Kimberling  
M. W. CLINE

Compass Declination  
Agency  
Party Chief  
Notekeeper  
Witnesses

OK  
JHL