

T295 RBW

DATE: 10-10-77

C
N 1/16 | S31
C
1

Condition Report Only
Not Found
 Renewed
Unrecorded
Surveyed In
Referenced Out

Previous Renewal #'s NONE - BLM RESURVEY 1965

Monument(s) Found: (Condition and Source) A 2" x 30" IRON PIPE
WITH BRASS CAP 6" ABOVE GROUND MARKED

C
N 1/16 | S31
C
1965

PIPE WAS NOT BENT BUT 30° FROM VERTICAL
AND BRASS CAP FASTENING BOLT WAS BROKEN

Accessories Found: (Condition and Source) A 11" DIA. W. OAK BEARS
N30°E 25¹/₂ FT. WITH A ROTTED OUT BLAZE. A 14" DIA. FIR
SNAG, 35 FT. TALL, BEARS S75³/₄°W 28° FT. WITH SCRIBING
"CN 1/16 S31 BT" IN SINGLE UNHEALED BLAZE.

#173 ✓

RENEWAL

Monument Set: (Procedure and Description) SECURED
RESET BRASS CAP
ON IRON PIPE AND RESET FROM BEARING TREES 5"
ABOVE GROUND AND ^{STAMPED} ~~MARKED~~ TO READ "T295 RBW"
NY16 | 531
RESET 1977
1965

New Accessories: (Description) A 8" DIA. CEDAR BEARS
S6°E 22⁹ FT., DOUBLE BLAZED AND SCRIBED "CN Y16 531
CS BT"

Location and Comments: 20°E Compass Declination
DCSO Agency
R. B. KIMBERLING Party Chief
R B Kimberling Notekeeper
M. W. CLINE Witnesses

OK
[Signature]