

T 29 S R 5 W

1/4 S 33 | S 34

DATE: NOVEMBER 1, 1977

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s CS FILE 2 1/2, VOL 3 PAGE 21, REN NO. 60 & 129

Monument(s) Found: (Condition and Source) 1 1/4" (I.D.) IRON PIPE

WITH PLOW SHARE ALONG SIDE. WE FIND NO RECORD OF

THESE MONUMENTS BEING SET FROM ORIGINAL EVIDENCE.

Accessories Found: (Condition and Source) S.T.S PER RENEWAL # 129

1. A W. OAK 20 NOW 24 INCHES DIAMETER BEARS S 52 1/2° W  
66 1/2 FEET. TREE HAS WELL HEALED DOUBLE BLAZE.

2. A MADRONE (LAUREL) 7 NOW 10 INCH DIAMETER TRIPPLE FORKED  
AT BASE BEARS N 3 1/2° E (REC N 4 1/2° E) 48 1/2 FEET.

SCRIBING VISIBLE ON PARTIALLY HEALED UPPER BLAZE, LOWER  
BLAZE WELL HEALED.

✓  
C.S. File No. 59/42-1 Page 1 of 1 ✓

FENCE CORNER BEARS N 55° E 2<sup>RD</sup> FEET FENCES

RUNNING N 60° W, N 30° E, 1' EAST.

NO ORIGINAL BEARING TREES FOUND.

RENEWAL

Monument Set: (Procedure and Description) AS WE CAN NOT  
FIND ANY RECORD TO INDICATE THAT THIS MONUMENT  
WAS SET FROM ORIGINAL BEARING TREES, AND  
THAT THIS POSITION IS WELL PERPETUATED WE  
DO NOT RENEW THIS CORNER.

New Accessories: (Description) NONE

Location and Comments:	<u>20° EAST</u>	Compass Declination
	<u>DCSO</u>	Agency
	<u>GARY L. LANGLITZ</u>	Party Chief
	<u>Larry P. M...man</u>	Notekeeper
	<u>PETE L. EARLE</u>	Witnesses

OK  
*[Signature]*