

U.S.P.C. PROP. COR.
 T 305 RIW
 35
 312
 RE 4287
 DO NOT DISTURB
 1961

DATE: 11-17-77

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #115 T30-1 #18 T29-1

Monument(s) Found: (Condition and Source) 2 1/2 ALUMINUM
CAP STAMPED AS SHOWN ABOVE.

Accessories Found: (Condition and Source) ORIGINAL CEDAR
NOW A 32" STUMP BEARS S85°E, 38.6' ^(RECORDED, S85°E, 39.4') SCRIBING
VISIBLE "RIW S2B" ON A PARTLY HEALED BLAZE,
A 8" DOUGLAS FIR BEARS S56°E, 22.5' ^{(RECORDED}
~~BEARING IS S36°E~~) HAS A SINGLE HEALED BLAZE. ^{Per #115}
A 15" DOUGLAS FIR BEARS S27°W, 27.0' / REC.
DIST. IS 27.5') SOME SCRIBING VISIBLE ON A
NEARLY HEALED BLAZE.

Page 1 of 1

#159 T30-1 #19 T29-1 U.S. File No. 59/42-17

U

A 8" DOUGLAS FIR BEARS N20°W, 42.6'
(RECORD DIST. 42.95') SCRIBING VISIBLE "5
BT T295 RIW". THE ORIGINAL
B.T. TO THE S.W. IS GONE. I
PLACED B.T. SIGNS ON ALL ACCESSORIES.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:

THIS CORNER LIES
ON A VERY STEEP
WEST SLOPE.

20°E

U. S. F. S.

DENNIS GAYLORD

" "

RANDAL LOPEZ

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK
[Signature]