

DATE: DEC 5, 1977

T275 RBW
S 1/4 S32

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s NONE - (1961 RESURVEY)

Monument(s) Found: (Condition and Source) A 2 1/2" DIA. IRON PIPE
WITH BRASS CAP SET 2" ABOVE GROUND, MARKED

" 5C
T275 RBW "
Y4532
1961

Accessories Found: (Condition and Source) A 51" DIA. CEDAR
STUMP, UPROOTED (STUMPHOLE) BEARS N 3° W (REC. N 8° W) 21⁸ FT.
WITH VISABLE SCRIBING "1/4 532 SC BT" IN A PARTIALLY
HEALED DOUBLE BLAZE.

52 X

Page 1 of 1

C. S. File No. 59/42-20

U

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A 38" DIA. FIR STUMP BEARS

N 39°W 37¹/₂ FT. WITH A BOAT SPIKE DRIVEN IN CENTER

MARKED "B02". A 42" DIA. FIR STUMP BEARS S 11¹/₂°W

38³/₄ FT. WITH A BOAT SPIKE DRIVEN IN TOP MARKED

"B01".

Location and Comments:

CORNER IS 30 FT.
SOUTH OF LOGGING
ROAD AT EDGE OF
TEMPORARY LANDING.

20°E

DLSO

R. B. KIMBERLING

R. B. Kimberling

S. J. FLAUSE

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK
[Signature]