

DATE: DEC 5, 1977

N 1/4 532
T27 1/2 S R8W

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #9 T27 1/2 #28 T27-8

Monument(s) Found: (Condition and Source) A 2 1/2" DIA. IRON PIPE

WITH BRASS CAP SET 12" ABOVE GROUND, MARKED

" 1/4 532 "
T27 1/2 S R8W
1961

Accessories Found: (Condition and Source) A STUMP HOLE BEARS

S72 1/2° E 30 ± FT. REMAINS OF TREE NOT FOUND. A 40" DIA.

HEMLOCK STUMP BEARS S36° W 70 ± FT WITH NO VISABLE BLAZE.

A 6" NOW 8" DIA. YEW BEARS S36° E (REC. S41° E) 17 ± FT,

SCRIBING "1/4 532 BT" VISABLE ON PARTIALLY HEALED

BLAZE. (Ren #9 T27 1/2) (Ren #28 T27)

#11 T27 1/2 - 8 X

#51 T27-8 X

RENEWAL

Monument Set: (Procedure and Description) STAMPED "N" ON

BRASS CAP TO READ "N 1/4 532"
T27 1/2 S R8W
1961

New Accessories: (Description) NONE

Location and Comments:

20°E Compass Declination
DCSO Agency
R.B. KIMBERLING Party Chief
R.B. Kimberling Notekeeper
S.J. FLAUSE Witnesses

OK
[Signature]