

COUNTY SURVEYOR'S
T26S R1W OFFICE
53/52
S10/S11

DATE: 1-19-78

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

1978

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) STONE, 16" x 10" x
8" & MARKED "X" ON TOP, SOLIDLY SET IN
THE GROUND & COVERED WITH DUFF.
5 ^{GROOVES} ~~NOTCHES~~ ON THE "J" (BROKEN S.E.
FACE) AND 2 GROOVES ON THE EAST
FACE.

Accessories Found: (Condition and Source) A 51" DOUG. FIR
BEARS N 30° W, 43.7' (RECORD N 31 1/2° W,
48.18') SCRIBING VISIBLE ON ~~PARTS~~
PREVIOUSLY OPENED BLAZE "26S R1W S38"
A 47" DOUG FIR BEARS N 7° E, 112.1'
(RECORD N 7° E, 111.54') B.T.'S TO THE
SOUTH ARE GONE WITHOUT A TRACE."

#82 X

C. S. File No. 59/46-6 Page 1 of 1

e

PLACED COUNTY B T SIGNS ON
ALL 5 BEARING TREES

RENEWAL

Monument Set: (Procedure and Description) MOVING

ORIGINAL CORNER STONE ASIDE, I SET
IN ITS PLACE A 2 1/2" BRASS CAP ON
A 1" G.I. PIPE. I BURY ORIGINAL
CORNER STONE ALONGSIDE. BRASS CAP
STAMPED AS SHOWN ON REVERSE.

New Accessories: (Description) A 11" DOUG. FIR BEARS
N 84° W, 9.1' SCRIBED "T265 RIW S3 CS BT"
ON A DOUBLE BLAZE. A 14" DOUG FIR
BEARS S 17 1/2° W, 31.8' SCRIBED "T265 RIW
S10 CS BT" ON A DOUBLE BLAZE. A 17" DOUG
FIR BEARS S 31° E, 32.3' SCRIBED "T265
RIW S11 CS BT" ON A DOUBLE BLAZE.

Location and Comments: CORNER LIES ON A
STEEP SOUTH ^{EAST} SLOPE
APPROX. 200'
NW OF THE OLD
NORTH UMPQUA
ROAD.

16 1/2° E Compass Declination
U. S. F. S. Agency
DENNIS GAYLORD Party Chief
" " Notekeeper
ROLAND SIMSHAUSER Witnesses
OK