

T26S R3W

DATE: 1-10-78

2 | 1
11 | 12

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s #97, 1963 BLM Resurvey

Monument(s) Found: (Condition and Source) FD: BRASS CAP ON 1" I. PIPE
EXTENDING 14" ABOVE GROUND, MARKED AS DESCRIBED IN REN. #97.

NO TRACE OF ORIGINAL CORNER POST.

Accessories Found: (Condition and Source) FD. ORIGINAL BT'S AS FOLLOWS:

AN ORIG. 60" D. FIR, NOW A 60" SNAG 20 FT. TALL, BEARS N 24¹/₄° W 99° FT.,
(REC. REN. #97, N 25° W 99° FT.)(ORIG N 45° W 99° FT.) NO MARKINGS FOUND AT
THIS TIME.

AN ORIG. 20" NOW 42" D. FIR, ALIVE AND WELL-HEALED, BEARS S 86³/₄° W
43⁶/₁₆ FT. (ORIG. S 88° W 43⁶/₁₆ FT.)(REC. REN. #97- S 88° W 43⁶/₁₆ FT.)

AND AN ORIG. 20" ~~NOW~~ FIR, NOW A 42' SNAG 30 FT. TALL BEARS N 55° E 40³/₄ FT.,

✓ U.S. BLM No. 59/96-17

CONTINUED: (REC. PER. ORIG. N 48°E 38 ³/₄ FT.) (REC. REN. #97 N 55°E 38 ³/₄ FT.).

BT'S MARKED BY COUNTY SURVEYOR (REN. #97) IN 1960 AND REDESCRIBED BY BLM IN 1963 WERE FOUND AS FOLLOWS:

AN ~~7~~⁷" NOW 8" D. FIR, ALIVE AND WELL-HEALED, BEARS N 62°E 25 ⁷/₈ FT. (REC. REN. #97 N 62°E 25 ³/₄ FT.).

A 14" D. FIR NOW A 12" SNAG, WITH BLAZE AND SCRIBING OBLITERATED BY PERSONS

RENEWAL

Monument Set: (Procedure and Description) NONE

(CONTINUED FROM ABOVE)

~~New Accessories:~~ (Description) UNKNOWN, BEARS S 50°W 19° FT.

A 19" NOW 22" D. FIR, ALIVE AND WELL-HEALED, BEARS S 79°E 16 ²/₈ FT. (REC. ~~REN. #97~~)

BLM RESURVEY S 78 ¹/₂°E 17 ⁸/₈ FT.).

AND AN 8" NOW 10" G. FIR ALIVE AND WELL-HEALED, BEARS N 54°W 16° FT. (REC.

BLM RESURVEY N 54 ³/₄°W 16 ²/₈ FT.).

Location and Comments:	<u>20° EAST</u>	Compass Declination
	<u>DOUGLAS COUNTY SURVEYOR'S OFF.</u>	Agency
	<u>GARY L. LANGLITZ</u>	Party Chief
	<u>Gary L. Langlitz</u>	Notekeeper
	<u>LARRY E. MONREAN</u>	Witnesses
	<u>FRANK C. SILAGY</u>	
		