

T325 R2W

DATE: 4-26-78

YELLOW KING #2 LODGE  
CORNER #1

MINERAL SURVEY #792

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) NO TRACE OF ORIGINAL FIR CORNER POST.

Accessories Found: (Condition and Source) FROM MINERAL SURVEY #792 (SURVEYED IN 1916) WE FIND THE FOLLOWING:

AN ORIG. 4" NOW 13" MADRONE (LAUREL), ALIVE WITH FAINT SCRIBE MARKS VISIBLE ON PREVIOUSLY OPENED, ROTTEN FACE, BEARS S 76 1/4° E 17 7/8 FT., (REC. S 83° 48' E 17 1/2 FT.).

AND AN ORIG. 8" NOW 42" D. FIR, ALIVE WITH FAINT SCAR OF WELL-HEALED BLAZE VISIBLE, BEARS N 1° W 44 25 FT., (OVER)

#1064

(Rec. N1°03'W 44<sup>25</sup> Ft.). WE BLAZE AND RESCRIBE THIS  
TREE " YK 2-1 MS 792 CS BT " ON A DOUBLE BLAZE ALONG  
THE WESTERLY EDGE OF THE SCAR OF THE ORIGINAL BLAZE.

RENEWAL

Monument Set: (Procedure and Description) AT A POINT WHICH AGREES  
WITH THE MEASUREMENTS TO THE ABOVE DESCRIBED ORIGINAL  
BEARING TREES, WE SET A 1" X 30" IRON PIPE, 28" IN THE  
GROUND ON A SOUTHWEST SLOPE, WITH BRASS CAP ATTACHED, MARKED.

DOUGLAS CO SURVEYOR

T 325

New Accessories: (Description)

MS 792  $\sqrt{\text{YK 2-1}}$

R2W

1978

WE MARK THE FOLLOWING NEW BT:

\*A 12" MADRONE SCRIBED " YK 2-1 MS 792 CS BT " ON A DOUBLE  
BLAZE BEARS S 57° E 35<sup>4</sup> FT..

Location and Comments:

20° EAST

Compass Declination

D. C. S. O.

Agency

GARY L. LANGLITZ

Party Chief

Gary L. Langlitz

Notekeeper

FRANK C. SILAGY

Witnesses

OK 