

GENERAL LAND OFFICE SURVEY  
U.S. 1/4 52 1917

DATE: 4/13/78

Condition Report On:  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) 2 1/2" BRASS  
CAP, STAMPED AS SHOWN ABOVE, ON A  
1" IRON PIPE. PIPE IS SOLIDLY SET &  
~~BRASS~~ BRASS CAP IS 12" ABOVE GROUND.  
I ADD "T29S R2W" TO BRASS  
CAP, BELOW THE "S2"

Accessories Found: (Condition and Source) A 15" DOUG. FIR  
BEARS S 73° 30' W, 17.16' (RECORD BEARING  
IS S 74° W) HAS A HEALED SCAR.  
A 8" CHINQUAPIN IS DOWN. STUMP  
BEARS S 57° 30' E, 17.0' (RECORD IS  
S 59° E, 16.5'). SCRIBING VISIBLE ON DOWN  
LOG, "1/4 S". PLACED B. T. SIGN ON  
FIR. & CHINQUAPIN LOG.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A 16" DOUG FIR.

BEARS S 35° E, 28.7' SCRIBED

" 1/4 S 2 CS BT" ON A DOUBLE BLAZE.

PLACED A COUNTY B.T. SIGN ON FIR

Location and Comments:

16° E

U.S. F.S.

DENNIS GAYLORD

" "

RANDAL LOPEZ

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK  
*[Signature]*