

Vol. 15
Pg. 6156
GLO

GENERAL LAND OFFICE SURVEY
T285
T295
R2W S36
S6
T295 R1W
1922

DATE: 3-16-78

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) 3 1/2" BRASS CAP ON A 3" IRON PIPE, Set Solidly IN GROUND. BRASS CAP STAMPED AS SHOWN ABOVE.

Accessories Found: (Condition and Source) (ORIG 5") A 10" DOUGLAS FIR WITH A HEALED BLAZE BEARS N 70° W, ^(Rec. N 73° W) 2.64' TO FACE & 2.9' TO CENTER OF TREE

A 24" CEDAR (ORIG 18") BEARS N 10° W, 45.54' HAS A HEALED SCAR.

PLACED COUNTY B.T. SIGNS ON

#120-729-1 x BOTH.
#93-729-2 x