

GENERAL LAND OFFICE  
U.S. SURVEY  
1/4 536  
1923

DATE: 3-16-78

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) 2 1/2" BRASS  
CAP ON 3/4" IRON PIPE SET SOLIDLY  
IN GROUND. BRASS CAP STAMPED  
AS SHOWN ABOVE. I ADD "T285  
R2W" TO BRASS CAP ABOVE THE  
1/4 536

Accessories Found: (Condition and Source) A 51" FIR STUMP  
WITH A RAILROAD SPIKE IN TOP. SPIKE  
BEARS N 52° W, 10.1' (NOT OF RECORD)  
A 45" CEDAR STUMP WITH A RAILROAD  
SPIKE IN TOP. SPIKE BEARS N 9° 30' W,  
14.7' (NOT OF RECORD) NO TRACE

REMAINS OF ORIGINAL B.T.'S

#99-728-2 PLACED COUNTY B.T. SIGNS

#99-729-2 ON BOTH STUMPS

Page 1 of 1

G.S. File No. 59/46-54C