

T29-1
with sec 6
only

J. S. GENERAL

LAND OFFICE SURVEY

(Vol 15
Pg. 6157
620)

DATE: 3-16-78

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

1/4
56

1922

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) 2 1/2" BRASS CAP
ON A 1" IRON ROD SET FIRMLY IN THE
GROUND WITH BRASS CAP FLUSH TO SURFACE
MATERIAL (DUFF)

THIS IS THE W 1/4 CORNER FOR
SECTION 6, ONLY T29S R1W. I ADD
"T29S R1W" TO BRASS CAP ON
EAST SIDE OF STAMPING 1/4 56.

Accessories Found: (Condition and Source) A 30" CEDAR
BEARS S 74° E, 12.9' (RECORD, 13.2')
HAS A HEALED BLAZE.

A 18" HEMLOCK BEARS N 77° E,
27.3' (RECORD 27.06') HAS A
HEALED BLAZE. PLACED COUNTY
B.T. SIGNS ON BOTH.

#121-728-1 X
#92-728-2 X

RENEWAL

Monument Set: (Procedure and Description) _____

NONE

New Accessories: (Description) _____

NONE

Location and Comments: _____ Compass Declination

18°E

U.S. F.S.

DENNIS GAYLORD

" "

RANDAL LOPEZ

Agency

Party Chief

Notekeeper

Witnesses

OK
[Signature]