

COUNTY SURVEYOR'S  
T24S R1E OFFICE

DATE: 5-18-78

Condition Report Only  
Not Found  
 Renewed  
Unrecorded  
Surveyed In  
Referenced Out

○ 1/4  $\frac{S18}{S19}$

Previous Renewal #'s 1978

Monument(s) Found: (Condition and Source) ORIGINAL CORNER  
STONE SET SOLIDLY IN PLACE & MARKED  
" 1/4 " ON <sup>NORTH</sup> ~~EAST~~ FACE. STONE MEASURES  
16" x 13" x 9"

○

Accessories Found: (Condition and Source) ORIGINAL 30"  
NOW 38" DOUG FIR BEARS N 21° 30' E, 40.5'  
(RECORD DISTANCE IS 25.08') HAS DOUBLE  
HEALED BLAZES.

○ ORIGINAL 24" FIR IS A 30" CEDAR  
WHICH BEARS S 42° 45' E, 43.8' (RECORD  
IS S 42° 30' E, 42.9') HAS DOUBLE HEALED BLAZES.

Page 1 of 1

This is a copy of a corner I renewed  
in Lane County - 1/2 mile from  
County Line,  
#1

C. S. File No. 10/11-9 c

PLACED BEARING TREE SIGNS ON  
BOTH B.T.'S

RENEWAL

Monument Set: (Procedure and Description) MOVING THE  
ORIGINAL CORNER STONE ASIDE, I SET IN ITS  
PLACE A 2 1/2" BRASS CAP ON A 1" IRON  
PIPE. BRASS CAP STAMPED AS SHOWN ON  
REVERSE. I BURY THE CORNER STONE  
ALONGSIDE THE BRASS CAPPED PIPE.

New Accessories: (Description) \_\_\_\_\_  
NONE

Location and Comments: 19° E Compass Declination  
U.S. F.S. Agency  
DENNIS GAYLORD Party Chief  
" " Notekeeper  
ROLAND SIMSHAUSER Witnesses

*OK [Signature]*