

T235 R4W

C14

S9

DATE: 5-24-78

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #12, M24-42

Monument(s) Found: (Condition and Source) A ^{4"x4"}~~3"x3"~~ SQUARED CEDAR

POST IS STAPLED IN FENCE WIRE, WITH SCRIBING "CEN SEC 9".

Accessories Found: (Condition and Source) A 14" NOW 16"^{DIA.} CEDAR STUMP

HAS BEEN PUSHED OVER, ORIGINAL POSITION APPROXIMATELY BEARS

S34°W 14 FT. A 6" NOW 18" DIA. CEDAR BEARS S83½°E 232 FT.

WITH A CHOPPED OPEN ^{BLAZE}FACE AND BARK SCRIBING "CEN".

#160 ✓

RENEWAL

Monument Set: (Procedure and Description) A 1" x 36" IRON PIPE WITH
A BRASS CAP SET 4" ABOVE GROUND AND MARKED

"DOUGLAS COUNTY SURVEYOR"
T235 R4W

C V4
59
1978

New Accessories: (Description) A 6" DIA. D. FIR BEARS N5°E
9^B FT., 1 ~~BARK~~ DOUBLE BLAZE AND MARK "C V4 59 T235 R4W
CS BT".

Location and Comments:

CORNER IS ON A SOUTH
SLOPE AND 12 FT. SOUTH
OF A FENCE CORNER
TO WEST AND NORTH,
S.E. CORNER OF A
CLEARCUT UNIT.

20°E
DCSO

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

R.B. KIMBERLING
~~R.B. Kimberling~~
D.L. EARLE

OK
[Signature]