

T 26 S  
R 6 1/4 S 25 | S 30 S  
W W

DATE: 7-11-78

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 18, 24

Monument(s) Found: (Condition and Source) A 3/4" IRON ROD

APPROXIMATELY 2 INCHES ABOVE GROUND.

Accessories Found: (Condition and Source) ORIGINAL BEARING TREE

1. A W. OAK 30 NOW 40 INCH DIAMETER BEARS S 66° E 74 1/2 FEET (REC. S 64 1/2° E). TREE HAS WELL HEALED BLAZE. TREE FROM RENEWAL #24

2. A W. OAK 10 NOW 16 INCH DIAMETER BEARS S 66 1/2° E 48 3/5 FEET. TREE HAS A WELL HEALED DOUBLE BLAZE.

c.s. 60/11-27

*[Handwritten signature]*

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

New Accessories: (Description) NONE

Location and Comments:

CORNER IS IN HORSE  
PASTURE WITH NO  
NEARBY FENCES. (AS  
THE PEOPLE LEASING  
THIS PROPERTY HAVE  
NOT BEEN PLEASED  
WITH OUR PRESENCE  
WE DO NOT REMONUMENT  
THIS CORNER )

19° EAST  
DOUGLAS Co. SURV. OFF.  
L. E. MURPHY  
Larry E. Murphy  
P. L. EARLE

Compass Declination  
Agency  
Party Chief  
Notekeeper  
Witnesses

OK  
*[Signature]*