

DATE: 8-31-78

COUNTY SURVEYOR'S  
T265 R1W  
526 | 525  
535 | 536  
1978  
OFFICE

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) ORIGINAL CORNER  
STONE, 4" x 7" x 12" & MARKED WITH ONE  
NOTCH ON THE EAST EDGE AND ONE NOTCH  
ON THE SOUTH EDGE, IS FIRMLY  
SET IN THE GROUND.

Accessories Found: (Condition and Source) A 26" DOUG. FIR  
BEARS N24°E, 25.8 FT (RECORD N22½°E, 26.4')  
SCRIBING VISIBLE ON PREVIOUSLY OPENED BLAZE.  
A 36" DOUG. FIR BEARS N22½°W, 19.3 FT  
(RECORD N25°W, 19.8 FT) HAS A HEALED  
BLAZE WHICH HAS BEEN PREVIOUSLY PARTIALLY  
OPENED. A 24" HEMLOCK BEARS S51½°W,

#89 X

20.2 ft. (RECORD  $554^{\circ}W$ , 27.06 ft) HAS  
A HEALED SCAR. 10 LK ERROR IN RECORD  
MEASUREMENT TO THIS B.T. A 28" DOUG FIR  
BEARS  $568^{\circ}E$ , 19.4 ft. (RECORD  $567\frac{1}{2}^{\circ}E$ , 19.14')  
HAS A PREVIOUSLY OPENED BLAZE WITH VISIBLE  
SCRIBING. (THIS TREE IS NOT TOO HEALTHY)  
RENEWAL

Monument Set: (Procedure and Description) REFERENCING THE  
CORNER STONE, I MOVE IT ASIDE AND SET  
IN ITS PLACE A 1 1/2" IRON PIPE WITH A  
2 1/2" BRASS CAP, MARKED AS SHOWN ON  
THE REVERSE SIDE, ATTACHED. I BURY  
THE CORNER STONE ALONGSIDE THE IRON PIPE.

New Accessories: (Description) \_\_\_\_\_

A 19" DOUG FIR BEARS  $560^{\circ}E$ , 43.9 ft.  
SCRIBED "T26S RIW 536 CS BT" ON A  
DOUBLE BLAZE.

PLACED COUNTY B.T. SIGNS ON ALL  
5 B.T.'s

Location and Comments:

$17\frac{1}{2}^{\circ}E$

U.S. F.S.

DENNIS GAYLORD

"

"

JAMES DAVIS

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses