

WIT. COR. 1/4 S 19 1/2 520

7325 R7W

DATE: 8-21-78 1st VISIT

(9-5-78 2nd VISIT)

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s 2

Monument(s) Found: (Condition and Source) FD. ORIG. PINE

COR. TREE (REC 60 IN PINE) NOW BURNT, KOTTED, AND

BROKEN OFF AT GROUND LEVEL. NO SCRIBING VISIBLE

FD: A 1" X 24" IRON BOLT ON WEST SIDE OF TREE.

(REN # 2)

Accessories Found: (Condition and Source) AN ORIG 60" PINE, NOW A

43" STUMP, BEARS N 34° E, 52.3 FT FROM CTR OF <sup>COE</sup> TREE TO

CTR OF <sup>BRG</sup> ~~COE~~ TREE (REC N 30° E., 49.5 FT) ROTTED BLAZE, NO

SCRIBING.

A ROOT HOLE BEARS S 30° W., 6° FT. WITH ORIG PINE

ALONG SIDE. NO SCRIBING VISIBLE, BRG 4 DIST FROM

CTR OF COR TREE TO CTR OF ROOTHOLE

#105X

Page 1 of 1

C. S. File No. 6017-1

c

AN 8 IN LAUREL (MADRONE), NOW 11 IN., BEARS N. 22° W., 19.3 FT  
(REG. N. 24° W.) WITH UNLIBLE SCRIBING ON PARTIALLY  
HEALED BLAZE. SCRIBING NOT READABLE. (KEN #2)

A 6 IN LAUREL (MADRONE), NOW ROTTED WITH ONLY FACE STANDING  
BEARS S. 55° E., 15.3 FT. UNLIBLE SCRIBING "2968 BT"  
(KEN #2) LAUREL MEASURED FROM CTR OF TREE TO I. BOLT  
RENEWAL

Monument Set: (Procedure and Description) REPLACE IRON BOLT WITH  
1" X 36" IRON PIPE WITH BRASS CAP AT REG. DIST FROM BT'S  
IN KEN #2. SET BOLT ON EAST SIDE OF CAP, WEST SIDE OF TREE.  
CAP BEARS N. 55° W., 2.5 FT FROM CTR OF OAK TREE. STAMPED  
"DOUGLAS CO. SURVEYOR"  
"T 325 R 7W" RETURNED TO FIND BLM ADDED  
CAP "1/4 S 19 & S 20" "WC 2.5 FT COR." TO CAP  
"1978"

New Accessories: (Description) AN 11" D. FIR, BEARS  
S. 40° E., 40.8 FT SCRIBED "1/4 S 20 CS BT" ON DOUBLE BLAZE  
RETURNED TO ADD "WC" AT TOP OF BLAZE.  
ON RETURNED SCRIBED ADDITIONAL TREE.

A 10" D. FIR, BEARS S. 71° W., 16.8 FT SCRIBED "WC  
1/4 S 19 CS BT" IN A DOUBLE BLAZE.

Location and Comments: 20° EAST Compass Declination  
DCSO Agency  
GARY LANGRISH 2ND VISIT KAREN REED 1st VISIT Party Chief  
KAREN REED Notekeeper  
FRANK C SILAGY Witnesses

OK  
[Signature]