

T295 RBW

DATE: 9-28-78

11 | 12
1/4

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 124

Monument(s) Found: (Condition and Source) NO TRACE OF ORIGINAL

CORNER POST. FOUND A 1" IRON PIPE EXTENDING 16" ABOVE GROUND, WITH

BRASS CAP ATTACHED, MARKED: COUNTY SURVEYORS OFFICE

T295 RBW

1/4 511 | 512

1966

Accessories Found: (Condition and Source) REMAINS OF AN ORIGINAL BT,

A 30" D. FIR, NOW A 40" STUMP, NO MARKINGS FOUND BEARS N 30° W 19^B FT.

AND REMAINS OF AN ORIGINAL BT, A 12" LAUREL, NOW A 17" DIAMETER 6 FOOT

TALL STUMP, PREVIOUSLY OPENED, NO MARKINGS VISIBLE, BEARS S 89° E

46^E FT., (REC. 589° E 44^E FT.).

BEARING TREES FROM RENEWAL # 124; A 9" LAUREL, NOW 10" AND UPROOTED,

ROOT HOLE BEARING APPROX. S 47° E 14^E FT. ~~AND~~ SCRIBING "1/4 512 CS BT"

#188 ✓

e

VISIBLE ON UNHEALED DOUBLE BLAZE, AND;

A 7" HEMLOCK, NOW 9" DIAMETER, 6 FOOT TALL STUMP WITH WELL-HEALED
DOUBLE BLAZE BEARS N 71° W 9[±] FT. (REC. N 76° W 9[±] FT.)

RENEWAL

Monument Set: (Procedure and Description) AT THE POSITION OF THE
FOUND 1966 MONUMENT AND THE EXACT CORNER POINT, WE RESET SAID
1966 MONUMENT TO EXTEND TWO INCHES ABOVE GROUND.

New Accessories: (Description)

A 7" D. FIR, SCRIBED "1/4 S 12 CS BT" ON A DOUBLE BLAZE, BEARS
S 43° E 34[±] FT., AND

A 8" G. FIR, SCRIBED "1/4 S 11 CS BT" ON A DOUBLE BLAZE BEARS
S 4° W 64[±] FT.

Location and Comments:

20° EAST.

Compass Declination

CORNER LOCATED IN LOGGED

DOUGLAS CO. SURVEYOR'S OFF.

Agency

AREA. PLACED LOCATION

GARY L. LAUGLITZ

Party Chief

POSTER APPROX. 175 FT.

DAVID J. JUNGLET

Notekeeper

WEST OF CORNER ALONG

FRANK C. SILAGY

Witnesses

LOGGING ROAD. PLACED

SURVEY MARKER POST AND

SIGN APPROX. ONE FOOT EAST

OF THE CORNER.

OK
[Signature]