

T295

DATE: 10-2-78

RBW S 12 $\frac{1}{4}$

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 1924 GLD RETRALEMENT (PC. 6009)

Monument(s) Found: (Condition and Source) NO TRACE OF ORIGINAL
CORNER POST. FOUND: AT THE CORNER POINT, A 1" IRON PIPE, FIRMLY
SET, EXTENDING 10" ABOVE GROUND ON A STEEP WESTERLY SLOPE, WITH
BRASS CAP ATTACHED, MARKED:

U. S. GENERAL LAND OFFICE SURVEY

$\frac{1}{4}$ S 12

1924

Accessories Found: (Condition and Source) REMAINS OF THE ORIGINAL
BEARING TREES AS FOLLOWS:

AN ORIG ~~10"~~^{10"} LAUREL (MADRONE), NOW AN 18" SNAG, NO MARKINGS
 VISIBLE ON A PREVIOUSLY-OPENED BLAZE, BEARS S 60° E 18⁵ FT.,
 AND AN ORIG. 36" FIR, NOW A 70" D. FIR SNAG, WITH FAINT SCRIBING
 " $\frac{1}{4}$ " VISIBLE ON DETERIORATING BARK BLAZE, BEARS N 3° W 73² FT.,
 (REC. N 7° W 73² FT.).

#179 ✓

C. S. File No. 60/17-10 Page 1 of 1

C

FROM THE 1924 G.L.O. RETRACEMENT, A 24" NOW 36" D. FIR, ALIVE WITH
WELL-HEALED SINGLE BLAZE, BEARS S 19½° W 37° FT..

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A 13" D. FIR, SCRIBED 1/4 SIZ
CS BT" ON A DOUBLE BLAZE, BEARS N 5° W 48° FT..

Location and Comments:	<u>20° EAST</u>	Compass Declination
	<u>DOUGLAS CO. SURVEYOR'S OFF.</u>	Agency
	<u>GARY J. LANGLITZ</u>	Party Chief
	<u>Gary J. Langlitz</u>	Notekeeper
	<u>FRANK C. SILAGY</u>	Witnesses
	<u>TERRIE PLOUFF</u>	

OK
JHL