

T315 RIW

DATE: 10/19/78

1/1024

520 | 521

ORE LIC# 222

1972

Previous Renewal #'s M 42-75

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Monument(s) Found: (Condition and Source) 3" BRASS

CAP ON A 2" IRON PIPE IN A MOUND OF
 STONE. THIS BRASS CAP WAS
 STAMPED "SNN 1/256" IN ERROR.
 I CHANGE TO READ "1/1024"

Accessories Found: (Condition and Source)

A 10" DOUG FIR BEARS S 62 1/2° W,
 22.6 FT. (RECORD S 62 1/2° E, 22.9 FT.)

I REMOVE "SNN 1/256" FROM FACE
 & PLACE SCRIBE 1/1024 IN ITS PLACE.

A 10" DOUG FIR BEARS N 36 1/2° E, 12.6 FT.

I REMOVE "SNN 1/256" FROM FACE

C.S. File No. C.S. 60/17-15

Page 1 of 1

C

& SCRIBE "1/1024" IN IT'S PLACE.

ALL OTHER SCRIBING ON BT'S

REMAINS THE SAME.

RENEWAL

Monument Set: (Procedure and Description) _____

NONE

New Accessories: (Description) NONE

Location and Comments:

CORRECTION MADE
BY DIRECTION
OF J. A. HOFFBUAR

19°E
DENNIS GAYLORD
" "
LORI COLE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
JHL