

DATE: 11/9/78

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s BLM Oct. 17, 1932

Monument(s) Found: (Condition and Source) _____

2 1/2" brass cap 6" above the ground in good condition mkd.:

U.S. GENERAL LAND OFFICE SURVEY

Penalty \$250⁰⁰ for Removal

T19S R10W

S33 | S34

S4 | S3

T20S

1952

Accessories Found: (Condition and Source) _____

13" D-Fir, brs. S26°W, dist. 7²'

13" D-Fir, brs. N29°W, dist. 11³'

12" D-Fir, brs. S54°E, dist. 13⁸'

17" D-Fir, brs. N50°E, dist. 6⁴'

#22 T19-10 2

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments: 20° E Compass Declination
Go down USFS Rd. #48 (USFS) Deputy USFS Surveyor Agency
to Section line post Ernest R. Alvarado Party Chief
for Township line. Colin Long Notekeeper
(Sec. Cor. for 32,33, Diane Lawson Witnesses
5,4 is just off road.)
Sec. Cor. for 33,34,4,3
is one mile East of Sec. Ernest R. Alvarado
line post.

*OK
JHL*