



DATE: Jan 18, 1979

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) ORIGINAL 30"

CEDAR IS NOW A 52" CEDAR, BEARS N85°W,
42.24 ft. TO FACE. FAINT SCRIBING
VISIBLE ON BARK BLAZE.

ORIGINAL 36" FIR IS A WINDFALL. (LYING ON
FACE) LOCATION OF FACE OF TREE WHEN
STANDING BEARS N65°E, 71.28 ft.

#109 T28-2 X
#185 T27-2 X

ORIGINAL 6" FIR B.T. IS GONE,

RENEWAL

Monument Set: (Procedure and Description) MEASURING FROM
FACE OF CEDAR & APPROX. FACE OF FIR AS
DETERMINED FROM ROOTWAD HOLE, I SET A
1 1/2" IRON PIPE 36" LONG, 24" INTO GROUND. A
2 1/2" BRASS CAP ATTACHED IS STAMPED AS
SHOWN ON REVERSE.

New Accessories: (Description) A 20" DOUG FIR
BEARS S75°E, 70.5 FT SCRIBED "AP CSBT"
ON DOUBLE BLAZES. A 14" DOUG FIR BEARS
N51°E, 65.6 FT, SCRIBED "AP CSBT" ON
DOUBLE BLAZES. PLACED COUNTY B.T.
SIGNS ON ORIGINAL & NEW B.T.'S

Location and Comments:

THIS CORNER FALLS
IN THE EDGE OF A
SMALL CREEK.
C.C. FOR SEC 3 & 4
IS A BRASS CAP
& BEARS S78°30'W,
112.4 FT. (RECORD,
WEST, 110)

20° E
U.S.F.S.
DENNIS GAYLORD
" "
LEE ZINK

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]