



DATE: MAY 3, 1979

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) ORIGINAL 14" FIR, Now A 15" DOUGLAS FIR, CORNER TREE HAS HEALED SINGLE BLAZES ON THE NE, SE, SW AND NW SIDES.

Accessories Found: (Condition and Source) ORIGINAL 20", Now 23" DOUG FIR BEARS N 49° W, 10.56 ft. HAS A SINGLE HEALED BLAZE. A ORIGINAL 16", Now 17" WHITE FIR BEARS S 19° W, 26.4 ft. SOME SCRIBING VISIBLE ON A NEARLY HEALED SINGLE BLAZE. A ORIGINAL 14", Now 16" WHITE FIR BEARS S 46° E, 17.82 ft. SOME SCRIBING VISIBLE

#2 ✓

ON A NEARLY HEALED SINGLE BLAZE.  
ORIGINAL 26", Now 29" DOUGLAS FIR  
BEARS N 75° 30' E, 26.4 FT. HAS A  
SINGLE HEALED BLAZE.

RENEWAL

Monument Set: (Procedure and Description) I SET A  
1 1/2" IRON PIPE ALONGSIDE THE CORNER  
TREE. A 2 1/2" BRASS CAP, STAMPED AS  
SHOWN ON THE REVERSE, IS <sup>LOCATED</sup> CENTERED  
1.0 FT. SOUTH OF THE CENTER OF THE  
CORNER TREE.

New Accessories: (Description) NO NEW  
ACCESSORIES

Location and Comments: 20° E Compass Declination  
D.S.F.S. Agency  
DENNIS GAYLORD Party Chief  
" " Notekeeper  
BILL WEST Witnesses

OK 