

N 1/4 - ⁵⁹516

T30S R4W

DATE: 8-20-70

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 44, 69, & 144

Monument(s) Found: (Condition and Source) A 1 1/4" AXLE PROTRUDING
.75 FT ABOVE GROUND SET BY EPPSTEIN IN 1928
(REN 44)

Accessories Found: (Condition and Source) NO ORIGINAL TREES FD.

A FIR STUMP APPROX 30" DIAM BEARS N 63° E,
16.5 FT DIST. STUMP BADLY KOTTED (REN 44, 69)

(REC N 71° E) A 16" R. FIR, NOW 18" BEARS

N. 30° E., 64.4 FT DIST WITH WELL HEALED DOUBLE
BLAZE (REN 144) A 46" R FIR, NOW 54" BEARS

N 19° W., 278.7 FT. WITH WELL HEALED BLAZE. (REN 144)

274 X

Page 1 of 1

G. S. File No. 60/37-13

✓

(REC. 275.4 FT) 276.4 FT TO FACE

RENEWAL

Monument Set: (Procedure and Description) _____

NONE

PREVIOUS RENEWALS DO NOT STATE

BRGS & DIST. FROM ORIG. TREES.

New Accessories: (Description) AB " D. FIR SCRIBED

" 1/4 S 16 CS BT IN A DOUBLE BLAZE BEARS S. 79° E.,

97.3 FT DIST. A 10" BROAD LEAF MAPLE

SCRIBED " 1/4 S 16 CS BT " IN A DOUBLE BLAZE BEARS

S 22° W, 141° FT DIST

Location and Comments:

19° EAST
DCSO
KAREN REED
Karen Reed
FRANK C SILAGY
PETER L. EARLE

Compass Declination
Agency
Party Chief
Notekeeper

Witnesses

OK 