

DATE: 10-2-79

T30S

R			R
6	1		S
W	12	6	W

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 19, 140 T30-6 #205 T30-5

Monument(s) Found: (Condition and Source) A 3/4" I. ROD BURIED  
18" UNDER GROUND (REN 205)

Accessories Found: (Condition and Source) AN 8 IN DIAM W. OAK  
NOW 12 IN DIAM. WITH WELL HEALED DOUBLE BLAZE BEARS  
S. 59° W., 143.6 FT. DIST. (REN 140) A 12 IN. DIAM. B. OAK  
NOW 14 IN. DIAM. WITH PARTIALLY HEALED DOUBLE BLAZE  
BEARS N. 65° W., 106.8 FT. DIST. (REN 140) A 3/4" I. ROD  
18 IN. ABOVE GROUND, 1.5 FT NORTH OF RR R/W FENCE  
BEARS N. 65° W., 49.6 FT DIST (REN 140) DRIVE ROD 10 IN.

#279 T30-5 ✓  
 #226 T30-6 ✓

C

FARTHER INTO GROUND.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A 1 1/2" x 1 1/2" x 48" ANGLE

IRON POST SET 24 IN. IN GROUND BEARS WEST, 59.9 FT.

DIST. POST IN RR/R/W FENCE, 2 IN. HIGH LETTERS

" X B O " CHISEL ON FACE OF EASTERLY CULVERT

HEADWALL UNDER S.P. TRACKS, " X " IS 0.65 FT BELOW

TOP OF 7.5 FT LONG HEADWALL, BEARS N.34° W., 144.9 FT. DIST.

Location and Comments:

19° EAST

COR IN LARGE

DCSC

PLOWED FIELD.

LARRY E. MOURGAN

Karen Reed

TERRIE PLOUFF

FRANK C. SILAGY

PETER L. EARLE

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK  
*JHL*