

DATE: 12/13/79

(T19-9 N1/16?)

1/16 17/16

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) Condition good.

5/8" iron rod 1' above the ground.

Accessories Found: (Condition and Source) _____

32" D-Fir, brs. N27°W, dist. 10⁸', healed face, surveyor's tag w/ Wilfred Haines' #239

17" D-Fir stump, brs. S84°E, dist. 15⁸', scribing visible, surveyor's tag w/ Wilfred haines' #239

6" red band and blazes painted on BT's

Attention signs on fiberglass fence posts placed

North and South of corner.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments: _____ 20°E _____ Compass Declination
From junction of USFS (USFS) Deputy Co. Surveyor Agency
Rd. #919 & #23, go 3.3 Ernest R. Alvarado Party Chief
miles on #919 to location Carol Dickison Notekeeper
poster on South side of road. for Sec. Cor for Colin Long Witnesses
8,9,17,16. Go South approx. Ernest R. Alvarado
300' to Sec. Cor. 1/16 Cor.
lies approx. 1380' South of Sec. Cor.
on West edge of clear cut, on steep North slope.

OK
JHL