

T235


DATE: 12-18-79

R	12	7	R
S	13	18	4
W			W

Condition Report Only
 Not Found
 X Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s ^{#22} 36, 109 T. 23-4 ^{T. 23-5} #14, 30 - 77

Monument(s) Found: (Condition and Source) A 3/4 IN. IRON ROD
 PROTRUDING 10 IN. ABOVE GROUND (ORIGINAL UNRECORDED)



Accessories Found: (Condition and Source) AN ORIG. 8 IN. DIAM.
 REDWOOD, NOW A 22 IN. DIAM, 2 FT STUMP, BEARS S. 84° W.,
 12.5 FT DIST. AN ORIG. 12 IN. DIAM. FIR, NOW A 32 IN. DIAM.
 STUMP AND BEARS N. 65° W., 27.1 FT. DIST. I CHOP
 OUT SCAR TO FIND VISIBLE SCRIBE "S 12" - AN ORIG.
 12 IN. DIAM FIR, NOW A 26 IN. DIAM STUMP, BEARS
 N. 20° E., 16.5 FT. DIST. AN ORIG. 12 IN. DIAM FIR, NOW

#110 T 23-5

#165 ~~T23-5~~ T23-4

TIPPED OUT BEAR S. 69° E., 25.1 FT DIST.
 A 12" DIAM. R. FIR, NOW A 12 IN. DIAM. 35 FT HIGH
 SNAG BEARS N 44° E., 27.7 FT. DIST. WITH VISIBLE
 SCRIBE " T 235 R 4 W S 7 CS BT " IN AN UNHEALED DOUBLE
 (CONT)

RENEWAL

Monument Set: (Procedure and Description) 1" x 36" J. PIPE
WITH BRASS CAP MARKED " DOUGLAS COUNTY SURVEYOR "

	R	T 235	R
WITH <u>3/4" F. ROD</u>	S	512 57	4
INSIDE PIPE.	W	513 518	W
		1979	

AT SAME POSITION AS ROD

New Accessories: (Description) A 7" DIAM. D. FIR
SCRIBED " T 235 R 4 W S 7 CS BT " IN A DOUBLE BLADE
BEARS N. 71 1/2° E., 117° FT DIST.

Location and Comments: 19 1/2° EAST Compass Declination
LOCATED AT FENCE DCSO Agency
COR. FEN - S & E. L. E. MONREAN (D) Party Chief
Karwin Reid, Deputy Notekeeper
STEPHEN FLAUSE (D) Witnesses
TERRIE PLOUFF
M. SHAWN MEANS
TERESA L. BULEY

original

T 23 S
 R 12 / 7 R
 S 13 / 18 4
 W W

DATE: 12-18-79

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

Accessories Found: (Condition and Source) BLAZE. (REN 36) AN

11 IN. DIAM. CEDAR, NOW A 12 IN. DIAM. 10 FT HIGH SNAG, BEARS
N. 78 1/2° W., 32.7 FT. DIST. WITH VISIBLE SCRIBE "T23S
RSW S12 CS BT" IN AN UNHEALED DOUBLE BLAZE. (REN 36)
(THE TWO BT'S FROM REN 36 WERE REC. AS SCRIBED
"1/4 S7 CS BT & 1/4 S12 CS BT")

A 7" DIAM. W. FIR, NOW 13 IN. WITH HEALED OVER
DOUBLE BLAZE BEARS N. 33° W., 42.3 FT. DIST (REN 109)

A 7" DIAM W. FIR, NOW 15 IN, WITH HEALED OVER
DOUBLE BLAZE BEARS S. 24° W., 50.3 FT. DIST. (REC
51.2 FT DIST) (REN 109) (CONT)

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments: _____

_____	Compass Declination
_____	Agency
_____	Party Chief
_____	Notekeeper
_____	Witnesses

DATE: 12-18-79

T 23 S
R
S 12/7
W 13/18
R
46
W

Condition Report Only
Not Found
 Renewed
Unrecorded
Surveyed In
Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

Accessories Found: (Condition and Source) AN 8" DIAM FIR, NOW
12" WITH WELL HEALED DOUBLE BLAZE BEARS S 21° E,
101.6 FT DIST (REL S 22° E, 102.5 FT) REN 109

