

DATE: 3/27/80

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s M 43-22

Monument(s) Found: (Condition and Source) T 19-16

Brass cap mkd.: E1/16 S25  
S36  
1971  
4185

Accessories Found: (Condition and Source) \_\_\_\_\_

(18") 21" Hemlock, brs. N23°W, dist. 18<sup>6</sup>', scribing visible (17.9')

(14") 16" Hemlock, brs. S56°E, dist. 17<sup>9</sup>', scribing visible (17.25')

RENEWAL

Monument Set: (Procedure and Description)

New Accessories: (Description)

BT's painted w/red 6" bands and blazes

Location and Comments:

20°E

Compass Declination

Go up USFS Rd. #23  
approx. 5.0 miles to  
location poster for C.C.  
S25&S36, T19S R10W.

Deputy Co. Surveyor

Agency USFS

Ernest R. Alvares

Party Chief

Colin Long

Notekeeper

Carol Dickison

Witnesses

Go North 10 ch.s to C.C.,  
then go East 1100' along  
posted line to E 1/16 Cor.

*OK*