

T 215 R 7 W

DATE: 4-22-80

S18	S17
S19	S20

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 107

Monument(s) Found: (Condition and Source) FD MONUMENT

AS PER REN 107

Accessories Found: (Condition and Source) ALL BT'S ARE

STUMPS NOW DUE TO LOGGING IN PROGRESS

DID FIND A <sup>12</sup> ~~13~~ IN. HEMLOCK, NOW 13, (REC. 14")  
 BEARS S. 34° W. 13.7 FT. DIST. (REC. S 34° W,  
 13.9 FT.) (REN 107 S. 36 1/2° W., 13.2 FT)

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

SET A 5/8" IRON ROD UNDER BLM BRASS CAP  
1.5 FT. UNDER GROUND

New Accessories: (Description) \_\_\_\_\_

A 48" DIAM. FIR STUMP BEARS N. 69° W.,  
26.4 FT. DIST. TO A PK NAIL SET IN NOTCH IN  
EASTERLY FACE OF STUMP. <sup>REM</sup>  
A 26 IN. DIAM. CEDAR STUMP N. 56° E., 26.5 FT.  
DIST. TO PK NAIL SET IN TOP.

Location and Comments: 19° EAST Compass Declination

DCSC Agency  
LARRY E. MONROE D&P Party Chief  
Karen Reed Dep. Notekeeper  
KAREN S. MOSLEY Witnesses

*OK [Signature]*