

T 32 S R 5 W

DATE: 4-23-80

$\frac{1}{4}$ S 21 * S 22

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 79, 170

Monument(s) Found: (Condition and Source) A 5/8 IN. PUNCHED
IRON ROD SET BY OSHD IN 1966. AT POINT
AS DETERMINED BY WENDEROTH TO BE THE 1/4 COR S21/S22
(1 IN. IRON PIPE SET BY WENDEROTH IN 1955 #79
WAS REPLACED WITH OSHD IRON ROD IN 1966)

Accessories Found: (Condition and Source) AN 8 IN. DIAM. W. OAK
NOW A 10 IN. DIAM., WITH WELL HEALED DOUBLE BLAZE
BEARS S. 44 1/2° E., 85.5 FT. DIST., (REN 170) A POWER
POLE # E2908 T 135 WITH PK NAIL AT BASE BEARS
S. 20° W., 41.2 FT. DIST. (REN 170)
AN UNRECORDED PUNCHED 5/8" IRON ROD BEARS N 23° W.,
37° FT. DIST. SAID ROD IN CENTERLINE OF FRONTAGE RD.

424X

G.S. File No. 61/6-34

SHEET Page 1 of 1C

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) A 13 IN. DIAM. W. OAK SCRIBED

" 1/4 S22 CS BT " BEARS S. 77° E., 88.5 FT. DIST.

A 48 IN. DIAM. CULVERT BEARS S. 76° E., 35° FT. DIST.

MEASUREMENT TAKEN AT TOP CENTER OF SOUTHERLY

END SAID CULVERT

Location and Comments: 18° 30' EAST Compass Declination

COP. LOCATED

DCSO

Agency

32.0 FT NORTH OF

LARRY E. MONTREAN DEP.

Party Chief

R/W FENCE,

KAREN REED, Rep.

Notekeeper

KAREN S. MOSLEY

Witnesses

OK [Signature]