

DATE: 4/28/80

T30S R5W

1/4  $\frac{S11}{S14}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 138, 182, BLM Resurvey 1969

Monument(s) Found: (Condition and Source) Monument has been removed we find depression in soil marked with stake and flagging.

No evidence of original BT's found.

Accessories Found: (Condition and Source) from renewal #138

We find 3 BT's a 6" now a 13" B.oak bears N7°E, 69<sup>3</sup>ft

(record N7°W, 69<sup>2</sup>ft corrected in renewal #182 to N7°E

69<sup>2</sup>ft recorded in BLM survey as N8<sup>1</sup>/<sub>2</sub>°E 69<sup>3</sup>ft.) has healed

double blaze no scribing visible. A 5" now a 9" W.oak

bears N26°E, 61<sup>2</sup>ft (as per record #138) has healed double

blaze no scribing visible. And a 24" now a 31" Madrone

#209 x

bears  $N 51^{\circ} W, 72.5$  ft. (original record #138 is  $N 51^{\circ} W, 75^{\circ}$  ft.  
(this appears to be a slope measurement), BLM record  $N 51^{\circ} \frac{3}{4} W, 71.9$  ft.)  
tree has healed double blaze no scribing visible.  
We retag all trees and mark tags as recorded here.

RENEWAL

Monument Set: (Procedure and Description) We checked bearings  
and distances from stake found in depression. We reference  
out the stake and replace with a standard DCSO brass cap on  
a 30" iron pipe. Cap is firmly set in soil and protrudes  $0\frac{1}{4}$  ft.  
from surface. Cap is marked

DOUGLAS COUNTY SURVEYOR

T305

$\frac{1}{4}$   $\frac{S 11}{S 14}$

R5W

1980

New Accessories: (Description)

No other suitable trees available. Existing trees are retagged  
as mentioned above.

Location and Comments:

19°E

Compass Declination

DCSO

Agency

Deputy Stephen John Flouse

Party Chief

Stephen John Flouse

Notekeeper

TERRIE PLOUFF

Witnesses

SAAWN MEANS

OK 