

DATE: 5/19/80

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 39, 109

86 T21-11

Monument(s) Found: (Condition and Source)

County brass cap in good condition, mkd.:

T20S
S32   S33 R
S5   S4 11
T21S W
1964

Accessories Found: (Condition and Source)

58" D-Fir stump(Orig.), brs. N78°E, dist. 30.3', healed face  
has been cut into

11" burnt Hemlock snag, approx. 50' high, brs. N62°E, dist. 20.4',  
open double blaze, scribing visible: 20S R11W, S3, CS BT

23" D-Fir, brs. N59°W, dist. 30.3', healed face w/double blaze

22" Hemlock, brs. S87°W, dist. 30.8', healed face

8" Fir snag, brs. S83°E, dist. 12.9', open face, scribing visible

10" burnt Hemlock, brs. S77°E, dist. 23.1', open face, scribing  
visible

10" Hemlock, brs. N72°E, dist. 42.2', open face, scribing visible

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

New Accessories: (Description) \_\_\_\_\_

Attention sign on metal fence post placed near corner

B.T.'s painted with red blazes and 6" bands

Area flagged with pink "Land Line" ribbon

Note: Distances are to side and center of trees at root crown.

Location and Comments:

20°E

Compass Declination

Go up USFS Rd. #4811  
approx. 2.5 miles to  
location poster on back  
of brown Sec. line post.  
From location poster,  
corner lies 250' South  
along blaze line.

Doug. Co. Deputy Surveyor  
Ernest R. Alvord  
Carol Dickison, Survey  
Bob Walters, NRA YACC

Agency USFS  
Party Chief  
Notekeeper  
Tech. Witnesses

OK  
*[Signature]*