

DATE: Aug 7, 1980

T265 R4W
SW COR
L DLG49

Section 33

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 7, 45

Monument(s) Found: (Condition and Source) From renewal #45

a DCSO brass cap on a 1"x30" iron pipe is firmly set, leaning slightly west and protruding 15" from the ground. The cap is marked "COUNTY SURVEYORS OFFICE"

From renewal #7 a

T 295 R4W
SW COR

10"x10"x18" sandstone set

L DLG49

1955

on the northeast edge of the brass cap monument. The sandstone is marked "CL 49 CS" on its northeast face and marked "x" on its top face.

Accessories Found: (Condition and Source) Search for original

bearing trees is fruitless; apparently old roadwork in the area destroyed any evidence of these trees. From renewal #7 a 12" W. oak now a 25" W. oak bears S51°W, 52⁶ ft. (record S52°W, 52⁶ ft); this tree has a well healed blaze which we partially open to find the scribing "L 49". And a 36" W. oak

#117X

